

Message

From: ZIFF, SARA [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=1CE282EB90B04EDD932CCDCEACDE7F9A-SZIFF]
Sent: 3/28/2016 8:57:16 PM
To: Sandoval, Angela [Sandoval.Angela@epa.gov]
Subject: RE: UTC/UTAS Rohr Riverside CA facility: PCB Site Characterization Work Plan

Thank you!

^^^^^^^^^^^^^^^^

Sara Ziff, P.E.
Project Manager
Corrective Action Section
U.S. EPA, Region 9
75 Hawthorne Street (LND-4-1)
San Francisco, CA 94105
(415) 972-3536
ziff.sara@epa.gov

From: Sandoval, Angela
Sent: Monday, March 28, 2016 10:31 AM
To: Armann, Steve <Armann.Steve@epa.gov>; ZIFF, SARA <ZIFF.SARA@EPA.GOV>
Subject: FW: UTC/UTAS Rohr Riverside CA facility: PCB Site Characterization Work Plan

non responsive per agreement with requestor

Angela Hendrichsen Sandoval, PE, PMP
Environmental Engineer
U.S. EPA, Region 9
75 Hawthorne Street (LND-4-2)
San Francisco, CA 94105
415-972-3831

From: Bernhardt, Carl@Waterboards [<mailto:carl.bernhardt@waterboards.ca.gov>]
Sent: Monday, March 28, 2016 10:20 AM
To: Sandoval, Angela <Sandoval.Angela@epa.gov>
Subject: RE: UTC/UTAS Rohr Riverside CA facility: PCB Site Characterization Work Plan

Thanks for the info. Here is an link to the article from the previous Sunday, where Ms. Newman is asserting that Rohr should be the RP for the Ag Park cleanup. Not sure If I had passed this article to you.

<http://www.pe.com/articles/dtsc-797480-pcbs-lee.html?page=1>

From: Sandoval, Angela [<mailto:Sandoval.Angela@epa.gov>]
Sent: Monday, March 28, 2016 10:04 AM
To: Bernhardt, Carl@Waterboards
Subject: FW: UTC/UTAS Rohr Riverside CA facility: PCB Site Characterization Work Plan

FYI

Angela Hendrichsen Sandoval, PE, PMP
Environmental Engineer
U.S. EPA, Region 9
75 Hawthorne Street (LND-4-2)
San Francisco, CA 94105
415-972-3831

From: Sandoval, Angela
Sent: Monday, March 14, 2016 5:07 PM
To: 'Curnock, David M UTCHQ' <David.Curnock@utc.com>
Cc: Thompson, Ron UTAS <Ron.Thompson@utas.utc.com>; Amig, Bruce UTCHQ <Bruce.Amig@utc.com>; Hammond, Travis (THammond@haleyaldrich.com) <THammond@haleyaldrich.com>; Bridget Morello <BMorello@progressiveec.com>; Armann, Steve <Armann.Steve@epa.gov>
Subject: RE: UTC/UTAS Rohr Riverside CA facility: PCB Site Characterization Work Plan

David,

Please find the attached document in response to your Site Characterization Work Plan received last month. Please feel free to call me with any questions.

Thank you,
Angela Hendrichsen Sandoval, PE, PMP
Environmental Engineer
U.S. EPA, Region 9
75 Hawthorne Street (LND-4-2)
San Francisco, CA 94105
415-972-3831

From: Curnock, David M UTCHQ [<mailto:David.Curnock@utc.com>]
Sent: Wednesday, February 17, 2016 3:05 PM
To: Sandoval, Angela <Sandoval.Angela@epa.gov>
Cc: Thompson, Ron UTAS <Ron.Thompson@utas.utc.com>; Amig, Bruce UTCHQ <Bruce.Amig@utc.com>; Hammond, Travis (THammond@haleyaldrich.com) <THammond@haleyaldrich.com>; Bridget Morello <BMorello@progressiveec.com>
Subject: UTC/UTAS Rohr Riverside CA facility: PCB Site Characterization Work Plan

Angela,

Per our discussion this afternoon, I am providing you with an electronic version (pdf) of site characterization work plan for PCBs at the UTC/UTAS Rohr Riverside, California facility. You will also be receiving a hard copy of this document which will be coming from Haley & Aldrich. Once you have had an opportunity to review the document, please do not hesitate to contact me with any questions. We look forward to working with you on this effort.

Best Regards

Dave

David M. Curnock CHMM
Remediation Manager

United Technologies Corporation

Tel.: 630-406-7737

Cell: 630-877-5837

e-fax: 860-660-6858

david.curnock@utc.com